

MONUMENT RECORD  
State of Indiana - County of Monroe

**Section:** 35

**Township:** 7 North


**Range:** 1 East

**Corner ID:** Polk Q-25

**Monument Description & Remarks:** 3" Aluminum cap, "T7N R1E, S.34/S.35". Survey Sign 1.5ft above ground at pt. B & 5ft above ground at pt. E

**References On File:** Kent Anderson survey notes (1983); Victor H. McCauley survey, U.S.D.A. Forest Service (1986), on file in Surveyor Office

RECOVERY TIE DRAWING  
Field Book 33 Page No. 31  
Field Book 41 Page No. 68



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 10th day of October, 2000.

*Kevin P. Enright*

Administered by the Monroe County Surveyor Review Board

Date: 4-7-2009



Index No. 217  
(Alphabetical - Numerical)

LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)

826-531

T. 7 N R. 1 E 2nd Mer. N.F. Hoosier County MONROE State INDIANA  
SECTION Corner common to sections 34 35 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_

Original monument \_\_\_\_\_  
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1984 By \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

|               |     |
|---------------|-----|
| TIN           | RIR |
| 34            | 35  |
| MONROE COUNTY |     |

LAURENCE COUNTY

○ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,  
etc.

3. Man hours spent in search

4. Do you think additional search might  
recover evidence? Yes ☐ No ☒

5. Signature Robert J. Stone

# Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
Object \_\_\_\_\_  
Record distance \_\_\_\_\_  
Measured distance \_\_\_\_\_

## Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

OLD BARB WIRE FENCE ON GROUND RUNS E-W  
2' S. OF CORNER MONUMENT

## Perpetuation Record

Monument and accessories established. Include brief description of area.  
SET A 30" ALUMINUM CONCRETE FILLED PIPE WITH  
A 3" DIA. ALUMINUM CAP FOR THE CORNER MONU-  
MENT. A ROCK CAIRN WAS BUILT AROUND IT.  
CORNER IS 3' ABOVE STREAM BED TO THE WEST AND  
14.5' N. OF OLD E-W RUNNING ROAD BED.

| W. OAK | MAPLE | B. OAK | HICKORY |
|--------|-------|--------|---------|
| 12"    | 5"    | 16"    | 10"     |
| 165°N  | N15°E | 563°E  | 513°W   |
| 29.2'  | 25.5' | 19.7'  | 24.3'   |

Certified corner registration certificate prepared: Yes ☐ No ☐  
Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_  
Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No. 2-17  
(Alphabetical - Numerical)LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)

GPO 806-924

T. 7N R. 1E 2nd Mer. N.F. Hoosier County Monroe State Ind  
Section Corner common to sections 34, 35, and \_\_\_\_\_

## EXISTING SURVEYS

## Original Government Survey

Year surveyed \_\_\_\_\_

Original monument wood post  
(Wood post, stone, pile of stones, pipe, etc.)

## Bearing Trees

|          |               |               |
|----------|---------------|---------------|
| Species  | <u>W. Oak</u> | <u>W. Oak</u> |
| Diameter | <u>30"</u>    | <u>6"</u>     |
| Bearing  | <u>N 7 E</u>  | <u>S 69 W</u> |
| Distance | <u>21 Ks</u>  | <u>24 Ks</u>  |

## Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Where filed or recorded \_\_\_\_\_

Monument \_\_\_\_\_  
(Original, concrete post, iron rod, etc.)

## Bearing Trees, Reference Objects

|          |       |
|----------|-------|
| Species  | _____ |
| Diameter | _____ |
| Bearing  | _____ |
| Distance | _____ |

## Original Evidence Found

Year of search 1972 By H. Deaton B. AyresMonument found No

## Original Bearing Trees Found


|          |       |
|----------|-------|
| Species  | _____ |
| Diameter | _____ |
| Bearing  | _____ |
| Distance | _____ |

## Evidence of Subsequent Corner Restoration Found

Year of search 1972 By H. Deaton B. Ayres

## Bearing Trees, Reference Objects

|          |       |
|----------|-------|
| Species  | _____ |
| Diameter | _____ |
| Bearing  | _____ |
| Distance | _____ |



Sketch

O Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,  
etc. photos, maps3. Man hours spent in search 3 hrs.4. Do you think additional search might  
recover evidence? Yes ☐ No ☒5. Signature R. Denton

## Relation of Evidence to Record Features Along Section Lines

Section line to sections 35-2Object Creek 31KsRecord distance E 13 ch.

Measured distance \_\_\_\_\_

## Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Found a N-S fence and an old road bed that followed S line of Section but no evidence of corner being monumented.

## Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

old deed mentions exception 12' by 462 ch. to road. It has 10 ch north of corner (Not measured)

Certified corner restoration certificate prepared:

Yes ☐ No ☒

Filed in county records at \_\_\_\_\_

Date \_\_\_\_\_

County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_

Which is filed at \_\_\_\_\_